PROPOSED NRC-DEVELOPED SCENARIOS

WITH FACILITY AND NRC COMMENTS

FOR THE PRAIRIE ISLAND INITIAL EXAMINATION - AUGUST 2002

Facility: _Pra	airie Island Scenario No.:1_	_	Op-Test No.: 2001301
Examiners:		Operators:	

Initial Conditions: <u>BOL</u>, recovery from reactor scram 24 hours ago, currently 15% power, <u>D2 OOS</u>, 12 AFW OOS, <u>Place Steam Dump in Stm. Pressure mode Instrument maintenance is performing troubleshooting on the Steam Dump Tave control mode</u>

Turnover: Recovery from Trip 24 hours ago. Raise power to 100% at maximum rate, MSRs are already in service.

Event No.	Malf. No.	Event Type*	Event Description
1		R (RO) N (BOP)	Raise reactor power 5-10%. RO will adjust reactivity by controlling boron concentration BOP will increase power by increasing turbine load, Lineup 13 Feedwater Heater drains for normal operation, Start one heater drain pump per 1C28.4, Heater Drains, and Shutdown the Condenser Spray System per 1C28.5.
2		I (RO) (BOP)	PT 431 (PZR press) fails high - take manual control of pressure and trip bistables (Simulator file number 97-03)
3		C (RO)	Charging pump trip-start another charging pump (Simulator file number 97-02)
4	<u> </u>	I (BOP)	PT-484 failure high - Manual control to shut steam dumps (Simulator file 99-05)
5		C (BOP)	11 Condensate pump motor stator HI temp - start a different condensate pump
6		M (All)	Uncontrolled depressurization of both S/G's - steam leak on A steam header results in manual reactor trip (if not already tripped) and stuck open S/G PORV on B S/G - Gets to ECA-2.1 (Simulator file 97-03)
7		C (BOP)	SI pump fails to start on SI signal-manually start SI pump

(N)ormal, (R)eactivity, (I)nstrument, (C)omponent, (M)ajor

Event Description: Raise Reactor Power 5-10%

<u></u>		
Time	Position	Applicant's Actions or Behavior
		RX Power Increase
	SRO	DIRECT Load increase at maximum allowed rate per 1C1.4.
		PERFORM or delegate the performance of Steps 5.1.1 to 5.1.6 of 1C1.4, "Power Operation."
	BOP	DETERMINE the Maximum Rate of Load Increase per Step 5.1.7A of 1C1.4, "Power Operation."
	RO	DETERMINE the Maximum Rate of Power Increase per Step 5.1.7A of 1C1.4, "Power Operation."
	ВОР	START the load increase as follows:
		-Select the desired load rate on the Turbine EH Control PanelVerify the turbine control VALVE POS LIMIT light is OFF. IF NOT, THEN lower the REFERENCE/SETTER until the light is OFFRaise the Valve Position Limiter to 100%.
		 -IF ITC is negative, <u>THEN</u> place turbine EH control in "IMP IN." -Set the desired turbine load on the SETTER display on the Turbine EH Control Panel using the reference control pushbuttons.
	RO	INITIATE an alternate dilution of the RCS per C12.5,"Boron Concentration Control," Step 5.4, as necessary.
	ВОР	WHEN T _{ave} shows an increase, <u>THEN</u> depress the turbine control GO pushbutton.
	RO	MAINTAIN T _{ave} and T _{ref} matched by varying the alternate dilution rate or performing alternate dilutions per C12.5 as necessary.

Op-Test No.: 2002301 Scenario No.: _1__ Event No.: _1__ Page 2_ of 2

Event Description: Raise Reactor Power 5-10%

Event L	Event Description: Raise Reactor Power 5-10%.		
Time	Position	Applicant's Actions or Behavior	
	ВОР	CUE: MSR's are already in service and 13 Feedwater heater drains are already aligned for normal operation.	
		START one heater drain pump per 1C28.4, "Unit 1 Heater Drains," Step 5.1.	
		SHUTDOWN the Condenser Spray System per 1C28.5, "Unit 1 Condenser Spray System," Step 5.2.	

Op-Test No.: <u>2001301</u> Scenario No.: <u>1</u> Event No.: <u>2</u> Page _1_ of _1_

Event D	Event Description: PT431 (PZR press) Fails High				
Time	Position	Applicant's Actions or Behavior			
		Pressurizer Pressure 1P-431 - Fails High EVALUATOR NOTE: The following annunciator will alarm when the malfunction is inserted: 47012-0408, "PRZR HI/LO Press Channel Alert"			
	RO	CRITICAL TASK: PLACE pressurizer pressure controller in MANUAL and stabilize pressure.			
		SELECT 2-1 (white-red) on channel selector switch.			
		RETURN pressure control to AUTO.			
		SELECT another channel on the pressurizer pressure recorder.			
	SRO	REFER to T.S.3.5.B & Table T.S.3.5-2A FU 7,9,10 and Table TS3.5-2B FU 1d (6 hr LCO for B/S tripping), and T.S. 3.10.J.b			
		Initiate investigation of reason for loss of Pressurizer Pressure 1P-431			
	BOP	TRIP and independently verify bistables IAW 1C51.3, "Instrument Failure Guide," Rev. 17. 1TC-407-C Over Temp ΔT Trip 1TC-407-D Over Temp ΔT Rod Stop 1PC-431-A Hi Press Trip 1PC-431-J LO Press Trip 1PC-431-I Unblock SI			
		1PC-431-G LO Press SI			

Op-Test No.: 2001301 Scenario No.: ___1_ Event No.: _3___ Page _1_ of _1

Event Description: 11Charging Pump OverloadTrip

Event	Event Description: 11Charging Pump OverloadTrip			
Time	Position	Applicant's Actions or Behavior		
	RO	EVALUATOR NOTE: The following annunciator will alarm when the malfunction is inserted: 47015-0103, "11 Charging Pump Overload Trip." RECOGNIZE reduced charging header and seal injection flow and START a standby Charging Pump IAW 47015-0103, C12.1 AOP1, "Loss of RCP Seal Injection," and C12.1 AOP2, "Loss of Charging		
		Flow To The Regen HX,": CRITICAL TASK: START 12 or 13 Charging Pump. CRITICAL TASK: INCREASE Charging Pump speed to maintain <2550# discharge pressure and seal injection flow ~8 gpm.		
	SRO	PLACE L/D in service IAW C12.1,"Letdown, Charging, and Seal Water Injection." ADJUST In-service Charging Pump speed to maintain 6-10 gpm seal injection flow to each RCP while balancing total Charging and L/D flow. PLACE In-service Charging Pump speed control in AUTO. INITIATE investigation of reason for loss of 11Charging Pump.		

Op-Test No.: <u>2002301</u> Scenario No.: _ 1 ___ Event No.: _4 ___ Page _1 __ of _1

Event Description: high PT-484 MS Header Pressure failure

	Event Description. https://example.com/pressure failure			
Time	Position	Applicant's Actions or Behavior		
		PT-484 MS Header Pressure failure high		
	RO	Identify failure of PT-484 MS Header Pressure high.		
		TAKE manual control to Steam Pressure controller 484 and CLOSE steam dumps.		
		Monitor and control reactivity transient.		
	3	CUE: When asked Troubleshooting with Tave mode circuitry is complete and ok to go to Tave mode.		
	SRO	DETERMINE Status of Maintenance on Tave mode circuitry and give direction to change steam dump control to Tave mode.		

Op-Test No.: <u>2002301</u> Scenario No.: <u>1</u> Event No.: <u>5</u> Page <u>6</u> of <u>10</u>

Event Description: 11Condensate Pump Motor Stator Temperature Increasing

Time	Position	Applicant's Actions or Behavior
		11Condensate Pump Motor Stator Temperature Increasing
		EVALUATOR NOTE: The following annunciator will alarm when the malfunction is inserted: C47009-0302, "11Condensate Pump Motor Stator HI Temp."
	ВОР	RESPOND to Alarm C47009-0302, "11Condensate Pump Motor Stator HI Temp."
		RECOGNIZE that 11Condensate Pump has high motor current.
		MONITOR stator temperature increase.
		SHIFT Condensate Pumps per 1C28.3, "Unit 1 Condensate System," Rev. 10W, Step 5.6, as temperatures continue to increase and prior to stator temperature reaching 140° C.
	SRO	Investigate reason for high stator current and temperature.

Op-Test No.: 2002301 Scenario No.: _1___ Event No.: _6&7__ Page_1_ of _5

Event Description: Steam leak on 1A SG safety header followed by 11FRV failure followed by 12 PORV failing open and an uncontrolled depressurization of both S/G's. SI pump does not auto start on SI signal.

<u> </u>	-	T
Time	Position	Applicant's Actions or Behavior
		Steam Leak on A SG safety relief valve header EVALUATOR NOTE: The following annunciator will alarm when the malfunction is inserted: C47022-0611, "Fire Detection Panel FP121 Fire Alarm."
	ВОР	RESPOND to Fire Alarm C47022-0611, "Fire Detection Panel FP121 Fire Alarm.": -Determine affected zone
		-Page Aux. Bldg. Operator
		-Bypass affected zone
		-Reset fire detection panel
		CUE: If the field operator is contacted to investigate the fire alarm in the Aux. Bldg. report that there is a large feather of steam coming from Loop A safety valve header.
		EVALUATOR NOTE: The 11 FRV will fail open. The operator will attempt unsuccessful to take MANUAL control of the Feedwater Regulating Valves from the control room.
		11 FRV Fails Open
	SRO	DIRECT operators to enter C28.2 AOP1, "Unit 1 Feedwater Regulating Valve Control Failure."
	ВОР	DISPATCH personnel to locally control at manual loading station.
		CUE: If the crew requests to take local control of 11 SG FRV then report that you are unable to approach the valve because of the steam leak in the area.

Op-Test No.: 2002301 Scenario No.: _1___ Event No.: _6&7__ Page_2_ of _5

Event Description: Steam leak on 1A SG safety header followed by 11FRV failure followed by 12 PORV failing open and an uncontrolled depressurization of both S/G's. SI pump does not auto start on SI signal.

<u> </u>		
Time	Position	Applicant's Actions or Behavior
	ВОР	REPORT to SRO that atmospheric conditions from steam leak prevent local manual control.
	SRO	DIRECT the reactor to be manually tripped before tripping due to high steam generator level.
		EVALUATOR NOTE: When a reactor trip is initiated, immediately increase the steam rupture on Loop A safety header. When SI occurs, fail open 12 SG PORV.
	RO	Manually TRIP the reactor
	ВОР	VERIFY turbine tripped.
		VERIFY Safeguards buses energized.
		CHECK if SI is actuated.
		VERIFY component alignment.
		EVALUATOR NOTE: 11 SI Pump fails to start
		CRITICAL TASK: Manually START 11 SI pump.
		EVALUATOR NOTE: SRO should direct transition to E-2 when it is recognized that there is a faulted S/G and then into ECA 2.1 when it is recognized that both S/Gs are faulted.
		E-2, "Faulted Steam Generator Isolation,"
	SRO	DIAGNOSE faulted SG and transition to E-2.
	SRO	DIAGNOSE that both SGs are faulted and transition to ECA -2.1.

Op-Test No.: 2002301_ Scenario No.: 1 __ Event No.: _6&7__ Page _3_ of _5_

Event Description: Steam leak on 1A SG safety header followed by 11FRV failure followed by 12 PORV failing open and an uncontrolled depressurization of both S/G's.

	 	
Time	Position	Applicant's Actions or Behavior
	RO/ BOP	ECA-2.1,"Uncontrolled Depressurization of Both Steam Generators." Check secondary pressure boundary: - MSIV's, FRV's, FRV B/P's, SGBD and FW CI valves closed Close steam supply valve from one SG to TD AFW pump IAW the note at the top of page 3 of the EOP Verify 11 SG PORV closed.
	ВОР	CUE: If field operator is dispatched to 12 SG PORV for local operation, report that Aux. Bldg. entry is unsafe based on steam conditions and you are unable to locally operate the PORV from the hot shutdown panel. Control feed flow to minimize RCS cooldown: -CHECK cooldown rate in RCS cold legs less than 100° F per hour. -THROTTLE AFW flow to a minimum of 40 GPM per SG with a narrow range of less than 5%. - ENSURE RCS temperature is stable or decreasing.

Op-Test No.: 2002301 Scenario No.: _ 1__ Event No.: _6&7___ Page _4 _ of _5

Event Description: Steam leak on 1A SG safety header followed by 11FRV failure followed by 12 PORV failing open and an uncontrolled depressurization of both S/G's.

<u></u>		
Time	Position	Applicant's Actions or Behavior
		EVALUATOR NOTE: If at least one SI or RHR pump is running and RCS pressure is less than 1250 psig than secure both RCPs
	RO	CHECK if RCPs should be stopped.
		CHECK PRZR PORVs available and closed and at least one block valve open.
	SRO	INITIATE periodic SG samples.
		VERIFY secondary radiation levels are normal.
	ВОР	STOP RHR pumps.
		RESET Containment Spray Signal and Stop CS pumps.
		CHECK RWST level greater than 33%
		RESET SI.
		RESET CI.
		ESTABLISH instrument air to containment
·		

Op-Test No.: 2002301 Scenario No.: _1_ Event No.: _6&7___ Page _5_ of _5

Event Description: Steam leak on 1A SG safety header followed by 11FRV failure followed by 12 PORV failing open and an uncontrolled depressurization of both S/G's.

			3 Ap 3 and an ancommoned depressurization of both S/G's.
	Time	Position	Applicant's Actions or Behavior
		RO	CHECK for SI termination criteria: -RCS subcooling greater than 20° FRCS pressure greater than 2000 and stable or increasingPZR level greater than 7%.
			VERIFY SI flow is <u>NOT</u> required.
I		ВОР	STOP SI pumps.
			TERMINATE SCENARIO: The scenario should be terminated once the crew has verified that SI is no longer required and secured SI.

Facility	Facility: _Prairie Island Scenario No.: _2 Op-Test No.:				
Examiners: Operators:					
conder	Initial Conditions: <u>Unit 1 is at 77% power. Load increase per C1.4 is in progress. Unit power was reduced to replace a bearing on 12 MFP. Equip OOS: 11TD AFW Pump, 12 EH oil pump, D5 Diesel Generator, 13 condensate pump to be used in an emergency only.</u> Turnover:Commence load increase per C1.4				
Event No.	Malf. No.	Event Type*	Event Description		
1		R (RO) N (BOP)	Load increase per C1.4 File 99-04 RO will adjust reactivity by controlling boron concentrate BOP will increase power by increasing turbine load.	on	
2		(BOP)	Diagnose a hotwell level transmitter failure and perform 0601 level goes to -7" BOP must open MV-32041.	actions IAW C47009-	
3		I (RO) N(Ruf)	N42 Power range failure high. Crew will respond per 10 in manual. El mene NH2 from Service #44		
4		C (BOP)	11 Component Cooling Water pump trip, 12 CCW pump automatically. BOP must recognize the failure of the start and manually start it.	fails to start indby pump to auto	
5 ***		C (RO)	Loss of Instrument Air to containment C34 AOP1 RO m and letdown, and manually control pressure to prevent to	cycling of PORV's.	
6	<u></u> _	M (ALL)	Loss of MFW, 12 MFW is manually tripped on loss of lul trips for unknown reason. *	pe oil 1/MFW pump	
7		C(RO) (BOP)	AFW starts and then trips - loss of heat sink - RO must scross connect Unit 2 AFW	stop RCPs - BOP must	
(N)orm	al, (R)	eactivity,	(I)nstrument, (C)omponent, (M)ajor		
	* Turbin Lule to auto two				

AX PT 468 Couls high gibrestituted howell to well traverson, then
Contrave des sources and all the hot well least drans, not well least drans, not well all and design affect.

**** and do get normal for Bop

*** Loss of instrument air was removed. Unnessory and well scenario too complex.

Op-Test No.:	Scenario No.: 4	Event No.: 3	Page 3 of
			1 age _0_ 01

Event Description: 11 SG pressure channel 1PT-468 failure high (11 SG PORV opens, must manually close PORV)

	,	The state of the s
Time	Position	Applicant's Actions or Behavior
	SRO/BOP	RECOGNIZE the failed transmitter by the following indications: - 11 SG pressure channel 1PT-468 failure high - Steam Flow indicator 1FI-464 failure high - 11 SG PORV opens
		PLACE 11 SG PORV controller in "MANUAL" and CLOSE valve
	SRO	DIRECT actions per 1C51.1, "Instrument Failure Guide" for Turbine 1st stage pressure channel 1PT-485 failure high
	ВОР	PERFORM actions per 1C51.1, "Instrument Failure Guide" for Tavg Loop 1B 1T-401 Channel Failure High: - VERIFY or place 11 SG PORV controller in "MANUAL" and CLOSE valve - VERIFY 11 SG level control operating properly in automatic
	SRO	REFER to the following Tech Spec requirements: - TS 3.5.B and Table 3.5-2B Functional Unit 1c
		EVALUATOR NOTE: The next step will probably NOT be performed due to 6 hours allowed before the bistables are required to be tripped DIRECT trip of the following bistables: - 1PC-468-A, "LO/LO PRESS SI" - 1PC-468-B, "LO PRESS ALARM"

Op-Tes	Op-Test No.: Scenario No.: _4 Event No.: _3 Page _4 of				
Event D	Event Description: 11 SG pressure channel 1PT-468 failure high (11 SG PORV opens, must manually close PORV)				
Time	Position	Applicant's Actions or Behavior			
	SRO	IF the Thermal Power Monitor is selected to Calorimetric input. THEN perform the following: CHECK TPM power unaffected by the steam pressure channel failure IF affected, THEN CHANGE TPM constant K202 from "0" (Calorimetric input) to "1" (NIS input) per C41.4, "ERCS NSSS Applications Program" AND NOTIFY ERCS computer group INITIATE Work Order to repair instrument MAKE necessary log entries			

Op-Test No.: ____ Scenario No.: ___ Event No.: ___

Page 3 of _

Event Description: 11 SG pressure channel 1PT-468 failure high (11 SG PORV opens, must manually close PORV)

ļ		The species, mast mandally close (OHV)
Time	Position	Applicant's Actions or Behavior
	SRO/BOP	RECOGNIZE the failed transmitter by the following indications: - 11 SG pressure channel 1PT-468 failure high - Steam Flow indicator 1FI-464 failure high - 11 SG PORV opens
		PLACE 11 SG PORV controller in "MANUAL" and CLOSE valve
	SRO	DIRECT actions per 1C51.1, "Instrument Failure Guide" for Turbine 1st stage pressure channel 1PT-485 failure high
	ВОР	PERFORM actions per 1C51.1, "Instrument Failure Guide" for Tavy Loop 1B 1T 401 Channel Failure High: - VERIFY or place 11 SG PORV controller in "MANUAL" and CLOSE valve - VERIFY 11 SG level control operating properly in automatic
	SRO	REFER to the following Tech Spec requirements: - TS 3.5.B and Table 3.5-2B Functional Unit 1c
	rol	EVALUATOR NOTE: The next step will probably NOT be performed due to 6 hours allowed before the bistables are required to be tripped DIRECT, trip of the following bistables: - 1PC-468-A, "LO/LO PRESS SI" - 1PC-468-B, "LO PRESS ALARM"

z		<u> </u>			
Op-Tes	t No.: So	cenario No.: 4 Event No.: 3 Page 4′ of			
Event D	Event Description: 11 SG pressure channel 1PT-468 failure high (11 SG PORV opens, must manually close PORV)				
Time	Position	Applicant's Actions or Behavior			
	SRO	IF the Thermal Power Monitor is selected to Calorimetric input, THEN perform the following: CHECK TPM power unaffected by the steam pressure channel failure If affected, THEN CHANGE TPM constant K202 from "0" (Calorimetric input) to "1" (NIS input) per C41.4, "ERCS NSSS Applications Program" AND NOTIFY ERCS computer group INITIATE Work Order to repair instrument MAKE necessary log entries			

Op-Test No.: 2002301 Scenario No.: __2_ Event No.: __1_ Page _1_ of _1_

Event Description: <u>Load increase per C1.4 RO will adjust reactivity by controlling boron concentration BOP will increase power by increasing turbine load.</u>

<u> </u>	 =	
Time	Position	Applicant's Actions or Behavior
	SRO	DIRECT Load increase to 100% at maximum allowed rate per C1.4.
	ВОР	Inform System Control Center of load increase. May inform Duty Chemist of load increase.
	RO	DILUTE using Alternate Dilute mode. When Tave shows a increase, Then increases turbine load by setting the SETTER and depressing GO.
	ВОР	OBSERVE turbine and generator limits
		Start the load increase as follows:
	'	SELECT the desired load rate on the Turbine EH Control Panel.
		VERIFY the turbine control VALVE POS LIMIT light is OFF. <u>IF</u> NOT, <u>THEN</u> lower the REFERENCE/SETTER until the light is OFF.
		RAISE the Valve Position Limiter to 100%. IF ITC is negative, THEN place turbine EH control in "IMP IN."
		SET the desired turbine load on the SETTER display on the Turbine EH Control Panel using the reference control pushbuttons.

Op-Test No.: 2002301 Scenario No.: _ 2 _ Event No.: _ 2 _

Page _1_ of __1_

Event Description: <u>Diagnose a hotwell level transmitter failure and perform actions IAW C47009-0601 level goes to -7" BOP must open MV-32041</u>.

<u> </u>		
Time	Position	Applicant's Actions or Behavior
	ВОР	EVALUATOR NOTE: The following annunciators will alarm when the malfunction is inserted: 47009-0601, "1A Condenser Hotwell LO LVL" RECOGNIZE 1A Condenser Hotwell level low alarm as the result
		of a failed controller. Refers to 47009-601:
		VERIFY normal makeup valve CV-31121 is open.
		CHECK for Leaks.
		VERIFY level in condensate storage tank is above T.S. minimum
		VERIFY CDSR dump to CLG Wtr Disch, CV-31123 is closed.
		IF level decreases to -7", THEN OPEN emergency makeup valve MV-32041.
		EVALUATOR NOTE: This event is designed so that level will go to 7". Opening MV-32041 with the condenser at vacuum results in a rapid flow rate of water from the CST. The AFW pumps may be inoperable because of the CST supply diverted to the condenser. The CST level will be inaccurate and may go to zero.
	SRO	VERIFY the BOP uses the alarm procedure.
		REVIEW the operability of the AFW system based on CST level IAW TS 3.4.B.

Op-Test No.: 2002301 Scenario No.: 2 Event No.: 3 Page _1__ of _4_ Event Description: N42 Power range failure high. Crew will respond per 1C51.2 RO must put rods in manual **Position** Time Applicant's Actions or Behavior **EVALUATOR NOTE:** The following annunciators will alarm when the malfunction is inserted: 47013-0101 NIS Power Range Positive Flux Rate Channel Alert 47013-0102 NIS Power Range HI Setpoint Channel Alert @v 132 47013-0103 NIS Power Range Overpower Rod Withdrawal Stop 47013-0203 NIS Power Range Channel Deviation 47013-0303 Computer Alarm Delta I Check Typer 47013-0403 Computer Alarm Flux Tilt Check Typer 1C51.2 Instrument Failure Guide RECOGNIZES the failed Power Range Instrument by the following RO indications: OBSERVES control rods stepping in. PLACE control rods in manual control and restore Tave equal to # Kong mugt be in auto

Event Description: N42 Power range failure high. Crew will respond per 1C51.2 RO must

put rods in manual

ļ		
Time	Position	Applicant's Actions or Behavior
	SRO	DIRECT that N-42 be removed from service.
	ВОР	REMOVES N-42 from service as follows:
		On the MISCELLANEOUS CONTROL AND INDICATION PANEL drawer:
		PLACE ROD STOP BYPASS switch in the N-42 position.
		PLACE POWER MISMATCH BYPASS switch in the N-42 position.
		PLACE UPPER SECTION CURRENT COMPARATOR DEFEAT switch in the N-42 position and VERIFY the Upper Section Channel Defeat Light is LIT.
		PLACE LOWER SECTION CURRENT COMPARATOR DEFEAT switch in the N-42 position and VERIFY the Lower Section Channel Defeat Light is LIT.
		On the COMPARATOR AND RATE drawer, PLACE COMPARATOR CHANNEL DEFEAT switch in the N-42 position and VERIFY Comparator Defeat Light is LIT.
		At N-42 POWER RANGE B drawer, REMOVE, and CONCURRENTLY VERIFY removal of the instrument power fuses.
		At N-42 POWER RANGE B drawer, REMOVE, and CONCURRENTLY VERIFY removal of the control power fuses.

Page _3__ of __4_

Event Description: N42 Power range failure high. Crew will respond per 1C51.2 RO must

put rods in manual

		
Time	Position	Applicant's Actions or Behavior
	BOP/RO	VERIFY the following annunciators are received:
		47013-0101 NIS POWER RANGE POSITIVE FLUX RATE CHANNEL ALERT
		47013-0102 NIS POWER RANGE HI SETPOINT CHANNEL ALERT
		47013-0201 NIS POWER RANGE NEGATIVE FLUX RATE CHANNEL ALERT
:		47014-0203 N42 NUCLEAR OVERPOWER ROD STOP BYPASSED Aqua Light
		VERIFY the following status lights LIT:
		44178-0206 PWR RNG LO Q-HI F NC42P
		44178-0207 PWR RNG HI Q-HI F NC42P
		44205-0204 PWR RNG HI F RATE NC42U/K
	SRO	REFER to the following Technical Specification requirements:
		TS 3.5.B & Table 3.5-2A FU 2a. 2b. 3. 4. 7. 8
		TS 3.10.B.9
		TS 3.10.C.4

Event Description: N42 Power range failure high. Crew will respond per 1C51.2 RO must

put rods in manual		
Time	Position	Applicant's Actions or Behavior
	SRO	DESIGNATE the following bistables to be tripped:
		1TC-406-A OVER POWER ΔT TRIP
İ		1TC-406-B OVER POWER ΔT ROD STOP
		1TC-406-C OVER TEMP ΔT TRIP
		1TC-406-D OVER TEMP ΔT ROD STOP
		EVALUATOR NOTE: The Chief Examiner will decide whether we need to observe the actual tripping of the bistables.

ppcnaix	<u> </u>	- Control Cont	
Op-Test No.: 2002301Scenario No.: 2 Event No.: 4 Page 1 of 1 Event Description: 11 Component Cooling Water pump trip, 12 CC pump fails to start automatically. BOP must recognize the failure of the standby pump to auto start and manually start it.			
Time	Position	Applicant's Actions or Behavior	
Time	BOP	EVALUATOR NOTE: The following annunciators will alarm when the malfunction is inserted: C47020-0101 "11 CC Pump Locked Out" 1C14 AOP1 Loss of Component Cooling REGONIZE that loss of 11CC pump did not result in an auto start of the 12 CC pump. CRITICAL TASK: START the 12 CC pump and refer to 1C14 AOP1: VERIFY RCP bearing temperatures below 200° F and CC Surge	
	SRO	Enters TS 3.0.C due to both CC pumps being inoperable. The failure to auto start makes the 12 CC pump inoperable and the requirements of TS 3.3.1 cannot be met. EVALUATOR NOTE: IF the BOP fails to diagnose the failure of the 12 CC pump to start in a timely manner and RCP bearing temperatures get above 200° F or the CC Surge Tank Level goes "off scale" THEN the reactor must be tripped per 1C14 AOP1.	
		C47015 - 0408 Reset ev 31204	

Op-Test No.:2002301 Scenario No.: _2___ Event No.: _5__

Page 1__ of _2_

Event Description: Loss of Instrument Air to containment C34 AOP1 RO must control charging and letdown, and manually control pressure to prevent cycling of PORV's.

	T = - = = = = 	T
Time	Position	Applicant's Actions or Behavior
		EVALUATOR NOTE: Instrument air isolation valve to containment CV 31741 fails closed. Will lose letdown, charging pumps fail to minimum speed, PZR spray valves fail closed, PZR PORV's will be on accumulators. C34 AOP1 Attachment A provides information on how components or systems will respond it will be of minimal help to operators due to the limited loss of Instrument Air.
		C34 AOP1; Loss of Instrument Air
	RO	RECOGNIZE loss of air to containment due to CV31741 failing closed (various valves in containment will reposition)
		REDUCE charging pump speed to limit discharge pressure
		CONTROL RCS pressure to prevent continued cycling of pressurizer PORV's.
		TURN OFF some or all pressurizer heaters to prevent PZR PORVs from lifting.
		CUE: Remain Ce gomen de roit
		Trip du reaction

Event Description: Loss of Instrument Air to containment C34 AOP1 RO must control charging and letdown, and manually control pressure to prevent cycling of PORV's.

<u> </u>	 	
Time	Position	Applicant's Actions or Behavior
Time	Position	Applicant's Actions or Behavior C12.1 AOP2: Loss of Charging to RHX -and/or- C12.1 AOP3; Loss of Letdown to the VCT EVALUATOR NOTE: Letdown Isolation Valves; CV-31226, CV- 31255, CV-31325, CV-31326, and CV-31327 should all fail closed. The operator will attempt to close them if they are not failed closed. PLACE charging in manual and reduce to minimum speed. CLOSE CV-31198; Charging Line Flow Control Valve and maintain 6-10 gpm to each RCP.
		IF 2 Charging Pumps are running THEN STOP one pump.

Op-Test No.: 2002301 Scenario No.: _2___ Event No.: _6__ Page _1__ of _3__

Event Description: Loss of MFW, 12 MFW is manually tripped on loss of lube oil 11 MFW pump trips for unknown reason.

 -		
Time	Position	Applicant's Actions or Behavior
		C47010-020 Feedwater Pump Aux Oil Pump LO Press
	ВОР	VERIFIES Aux Oil Pump running
		DISPATCH operator locally to Check for leaks.
		<u>CUE</u> : Field operator reports there is a large amount of oil on the skid and on the floor. After this cue the lo-lo pressure alarm comes in.
	SRO	In preparation for stopping the 1/2 Main FWP, DIRECT power decrease to a turbine load of 330 MWe per 1C1.4 AOP1, "Rapid Load Reduction - Unit 1"
		EVALUATOR NOTE: Because of the loss of instrument air the RO will be forced to emergency borate IAW C12.5 AOP1, "Emergency Boration of The Reactor Coolant System"
	RO	BORATE the RCS as necessary to maintain control rods above the insertion limit and to control delta I within limits:
		POSITION the Control Switches for the BATP aligned to services as follows:
		11BATP - CS-46163, 11 BA XFER PMP SPEED CONT CS, to "FAST."
		CS-46161, 11 BA XFER PMP CS, to "START."
		12 BATP - CS-46164, 12 BA XFER PMP SPEED CONT CS, to "FAST."
ļ		CS-46162, 12 BA XFER PMP CS, to "START."
		POSITION the recirculation control valve HC to 50% on the BAST aligned to services: 1HC-105 or HC-104

11 mrw oil problems - operater reguls wit - over decides to his - often top other morn my year avery Op-Test No.: 2002301 Scenario No.: 2___ Event No.: __6 _ Page _2__ of _3__

Event Description: <u>Loss of MFW, 11 MFW is manually tripped on loss of lube oil 12 MFW pump trips for unknown reason.</u>

<u> </u>			
Time	Position	Applicant's Actions or Behavior	
	RO	OPEN MV-32086, "Emergency Boration to Charging Pump Suction" using CS-46297	
		VERIFY boric acid flow on 1YIC113, Emergency Boration Integrator	
		WHEN the desired amount of boric acid has been added THEN CLOSE MV-32086 using CS-46297	
	ВОР	REDUCE turbine load in Automatic <u>OR</u> Manual: - Automatic:	
		SELECT the desired load rate on the Turbine EHC panel SET the desired turbine load on the "SETTER" display on the Turbine EHC Panel using the reference control pushbuttons DEPRESS the turbine control "GO" pushbutton Manual:	
		DEPRESS the turbine control "TURBINE MANUAL" pushbutton DEPRESS the "CV * " pushbutton until the desired turbine load is reached.	
	\nearrow	いからと 本にら も 12 所知 りから C47010-0102 11 Feedwater Pump Aux Oil Pump LO-LO Press	
		CUE: Once operators start to reduce power 12 MFW pump trips for unknown reason and the reactor will trip on LO-LO-SG level or will be manually tripped. TURBING fulls to outer try i mamae TRY	
		TURBINE fulls to outer two i Manual TRED 1E-0, "Reactor Trip or Safety Injection" & CV'S reval	لمه لمو
	SRO	DIRECT actions per 1E-0, "Reactor Trip or Safety Injection" مراها المالية الم	(6)
	RO	الملاحة VERIFY Reactor Trip or Manually Trip the Reactor:	

Op-Test No.: 2002301 Scenario No.: _2 ___ Event No.: _6__ Page 3 _ of _3__

Event Description: <u>Loss of MFW, 12 MFW is manually tripped on loss of lube oil 11 MFW pump trips for unknown reason.</u>

		
Time	Position	Applicant's Actions or Behavior
	ВОР	VERIFY Turbine Trip
		VERIFY Both Safeguards Buses Energized
		CHECK if SI is Actuated
	SRO	ANNOUNCE Reactor Trip
		NOTIFY Station Manager and Site Emergency Coordinator
		ENSURE communication with NRC is established within 1 hour
		After Verification that SI is not required transition to 1ES-0.1 REACTOR TRIP RECOVERY
		Establish conditions to control RCS temperature at 547° F
	ВОР	Establish conditions to control RCS temperature at 547° F
		Check MSIV's -OPEN
		Place Steam Dump in "STM PRESS" Mode
	RO	Check RCS Temperature
	ВОР	Notify turbine building operator to isolate Unit 1 MSRs per ATT J.
		Check cooling water pressure Loop A AND Loop B - GREATER THAN 75 PSIG
		Tokon stop valur net dosel closs cardral values
		closs carrel values

- Wait till step 12 to trip AFN grap Becam I Red BAHI Op-Test No.: 2002301 Scenario No.: 2 ___ Event No.: __7___ Page _1 _ of _3_

Event Description: AFW starts and then trips - loss of heat sink - RO must stop RCPs and

depressurize RCS - BOP must depressurize SG's and feed with condensate

<u></u>	The second of th			
Time	Position	Applicant's Actions or Behavior		
		EVALUATOR NOTE: After the operators have verified proper AFW flow the running AFW pump will trip due to an electric fault on the pump which will preclude it being restarted. The following annunciators will alarm when the malfunction is inserted: C47010 - 0107, "12 AFWP LOCKED OUT."		
	SRO	DIRECT transition to FR-H.1, Loss of Secondary Heat Sink.		
		FR-H.1, Loss of Secondary Heat Sink		
	RO	VERIFY secondary heat sink is required. RCS pressure - GREATER THAN ANY INTACT SG PRESSURE RCS hot leg temperature - GREATER THAN 350° F		
		CHECK for secondary heat sink, if none stop RCPs and skip directly to bleed and feed. Wide range level in either SG - GREATER THAN 9% PRZR pressure - LESS THAN 2335 PSIG		
		STOP both RCPs		
	ВОР	RESTORE AFW flow:		
		DISPATCH operator to determine cause of the AFW pump trip and locally restore AFW.		
		CUE: Field operator reports that the ground fault relay is up at the 12 AFW pump breaker and he cannot restore AFW		
	SRO	DIRECT that AFW be cross-tied to Unit 2.		

12:18

12:22

Appendix D

Operator Actions Form ES-D-2 (R8, S1)

Op-Test No.: 2002301 Scenario No.: _2___ Event No.: _7__ Page 2_ of _3__

Event Description: <u>AFW starts and then trips - loss of heat sink - RO must stop RCPs and depressurize RCS - BOP must depressurize SG's and feed with condensate</u>

<u></u>		
Time	Position	Applicant's Actions or Behavior
	ВОР	CROSS-CONNECT AFW from Unit 2 IAW 1C28.1, Step 5.7.
		PLACE CS-46425, 12 MD AFWP control switch in "PULLOUT."
		PLACE CS-46785, 21 MD AFWP selector switch in "MANUAL."
		STOP 21 MD AFWP, if running using CS-46770.
		REQUEST that Unit 2 operators CLOSE 21 MD AFW Pump valves to the Unit 2 S/G
		CUE: Unit 2 reports that MV-32383 and MV-32384 are closed.
		CLOSE 12 MD AFW Pump discharge valves to the Unit 1 SG's
		MV-32381 using CS-46316 MV-32382 using CS-46317
		DIRECT field operator to reposition the following valves:
		CLOSE AF-13-4 OPEN AF-13-1 and 2AF-13-1
		CUE: Field operator reports AF-13-4 closed and AF-13-1 and 2AF-13-1 open
		REQUEST the start of 21 MD AFW Pump
		<u>CUE</u> : Unit 2 reports that the 21 MD AFW Pump has been started.
İ		

Op-Tes	Dp-Test No.: 2002301 Scenario No.: 2 Event No.:7 Page _3 of _3		
Event Description: AFW starts and then trips - loss of heat sink - RO must stop RCPs and depressurize RCS - BOP must depressurize SG's and feed with condensate			
Time	Position	Applicant's Actions or Behavior	
		CRITICAL TASK: THROTTLE flow to Unit 1 SGs as necessary to maintain desired SG level using MV-32381 and MV-32382 TERMINATE SCENARIO: When AFW has been cross tied to	
		Unit 2	

Facility: Prairie Island		and	Scenario No.: Op-Test No.:		
Examiners: Operators:					
Initial Conditions:Unit 1: 100% Power, End of Cycle, Equilibrium Xenon, RCS baren =157 Breaker 16-10 (Bus 16/Bus 26 Bustie) is OOS. Steam Generator tube leakage of 4 GPD in 11 SG. Unit 2: 100% power steady state operation					
<u>lust stan</u>	<u>ea ana the</u>	nd 13 Heat 12 HD Pur 2 HD Pump	ter Drain Pumps are presently running. The 13 HD Pump was mp was shutdown so that preventive maintenance can be		
Event No.	Malf. No.	Event Type*	Event Lovell or additional Description		
1	RXOTC	I (RO)	Loop B Tcold transmitter failure high (Rods step in and Charging Pump in "AUTO" increases to maximum speed; must place rod control in "MANUAL")		
2	(5%)	C(RO)	maximum speed; must place rod control in "MANUAL") Pressurizer PORV (CV-31232) leaking (requires isolation)		
3	\$ X 14B (at 80% power)	I (BOP)	12 SG FW Reg Valve controller fails "as is" in AUTO (will need to control 12 SG level in "MANUAL")		
4	T2804 A (TRG 5) FW 13A (at 70% power, TRG 6)	R (RO) N (BOP)	High stator temperature on 11 Main Feedwater Pump (81°F to 150°F on 14) (requires turbine load decrease to 330 MWe, since will need to shutdown pump) (786 5) 11 Main Feedwater Pump trip during load reduction (will need to rapidly reduce turbine load).		
5	FW 19A (7867)	M(ALL)	Feedwater line break on 11 SG inside containment (300 444 1767)		
6	T(06 (Time 0)	C(BOP)	Failure of turbine to AUTO trip on Reactor Trip (will require MANUAL turbine trip)		
7	RP09A RP09B (Timeo)	C(RO)	Failure of SI to AUTO actuate (will require MANUAL actuation of SI)		
8	RP05 (Time 0)	C(BOP)	Failure of Containment Isolation to AUTO actuate on SI (containment Isolation)		
9	5602A	M(ALL)	SGTR on 11 SG when SG is fully depressurized (300 gpm) Requires entry into 1E-3 and then 1ECA-3.1)		
(N)ormal, (R)eactivity, (I)nstrument, (C)omponent, (M)ajor					

per licensee input.

Concur. Changes incorporated.
NVslos

Op-Test No.: Scenario No.: _3 Event No.: _1 Page _1 of				
Event D	Event Description: Loop B Tcold transmitter failure high (Rods step in and Charging Pump in "AUTO" increases to maximum speed; must place rod control in "MANUAL")			
Time	Position	Applicant's Actions or Behavior		
	SRO/RO RO RO	EVALUATOR NOTE: The following annunciators will alarm when the maifunction is inserted: - 47012-0104, "REACTOR COOLANT SYSTEM HI TAVG" - 47012-0304, "REACTOR COOLANT SYSTEM AT DEVIATION" - 47013-0305, "AUCTIONEERED TAVG-TREF DEVIATION" - 47013-0305, "AUCTIONEERED TAVG-TREF DEVIATION" RECOGNIZE the failed transmitter by the following indications: - Tavg Loop B failed high (βιος) - ΔΤ Loop B failed low (βιος) - Rods stepping in PLACE rod control in "MANUAL" DIRECT actions per 1C51.1, "Instrument Patiture Guide" for Tavg Loop 1B 1T-40/2 Channel Failure High 3 PERFORM actions per 1C51.1, "Instrument Failure Guide" for Tavg Loop 1B 1T-40/3 Channel Failure High: - VERIFY or place rod control in "MANUAL" and maintain Tavg equal to Tref - PLACE charging pump speed control in "MANUAL" and maintain pressurizer level - SELECT Bed channel on the Tavg defeat switch and pull out - RETURN rod control and charging pump speed to "AUTO"		
	RO	Add step to reflect performing actions for ARP 47012-0104, "REALTOR COCLANT STORM HI TAVE".		

Changes incorporated.
Changes incorporated.
Milator

Op-Test No.: ____ Scenario No.: __3 Event No.: __1 Page _2 of _ Event Description: Loop B Tcold transmitter failure high (Rods step in and Charging Pump in "AUTO" increases to maximum speed; must place rod control in "MANUAL") and changing purp speed control Time **Position** Applicant's Actions or Behavior SRO REFER to the following Tech Spec requirements: TS 3.5.B and Table 3.5-2A Functional Units 7 and 8 TS 3.5.B and Table 3.5-2A Functional Units 5d and 6c **EVALUATOR NOTE:** The next step will probably NOT be performed due to 6)hours allowed before the bistables are required to be tripped IRCH RO DIRECT_trip of the following bistables: - 1TC-405-A, "OVER POWER ΔT TRIP" Change in - 1TC-405-B, "OVER POWER ΔT ROD STOP" - 1TC-40g-C, "OVER TEMP ΔT TRIP" raflect - 1TC-405-D, "OVER TEMP ΔT ROD STOP" - 1TC-40/A, "HI TAVG ALARM" correct - 1TC-401-D, "LO TAVG MN STM ISOL" bistables for the 1TC-40%-F, "LO TAVG FW ISOL" failed che CUE: JPC INITIATE Work Order to repair instrument will be there in one (i) har MAKE necessary log entries The IRC Tech is out in Trains erihereement FOLLOWUP QUESTIONS: EVALUATOR NOTE: After the scenario is complete, a follow up question could be asked as to what instrument failed (i.e. Loop B Toold failed high, since Loop B Tavg failed high and Loop B AT failed low)
the following questions should be asked of the ROCAL SRD: 1) What instrument failed?

ANOWER: Loop B Tono failed high, since Loop B Tong
failed high and Loop BAT failed low. 2) What bistables actually tripped (if any) due to the

ANSWER : None

Chinges incorporated.

Chinges incorporated.

Malos

Op-Test No.: ____ Scenario No.: __3 Event No.: __2 Page 3 of Event Description: Pressurizer PORV (CV-31232) leaking (requires isolation) Time **Position** Applicant's Actions or Behavior **EVALUATOR NOTE:** The following annunciator will alarm when the malfunction is inserted: 47012-0506, "PRZR POWER RELIEF LINE HI TEMP" 47012-0606, PRER SAFETY VALVE A OR BHITTEMP **SRO** DIRECT or maintain overview of actions for leaking PRZR PORV per ARP 47012-0506. "PRZR POWER RELIEF LINE HI TEMP" **EVALUATOR NOTE:** The operator may isolate Block Valve MV-32195 or MV-32196 FIRST at his discretion to find the leaking PRZR PORV. PRZR PORV CV-31232 is the leaking PORV. PERFORM actions per ARP 47012-0506, "PRZR POWER RELIEF RO LINE HI TEMP" (ISOLATE PRZR PORVs one at a time with block valves to determine which valve is leaking): - CLOSE Block Valve MV-32195 to isolate PORV CV-31231 OBSERVE relief line temperature (NO decrease observed) red to - RESET acoustic monitor light . OPEN Black Veloc MV-32195 work CLOSE Block Valve MV-32196 to isolate PORV CV-31232 OBSERVE relief line temperature (decrease observed) RESET acoustic monitor light. REFER to Tech Spec 3.1.A.2.c (within one hour either restore SRO the PORV to OPERABLE status or close the associated block valve with power maintained to the block valve) arvenfy claved DIRECT RO to close PRZR PORV Block Valve MV-32196 to isolate leaking PORV CV-31232 and to maintain power to valve Charges incorporated.

additural alam elect cones in

should unrisolate 1st valve Lefore going to 2nd valve

Op-Tes	t No.: So	cenario No.: 3 Event No.: 3 Page 4 of	
Event D	escription: 12 (wil	SG FW Reg Valve controller fails "as is" in AUTO I need to control 12 SG level in "MANUAL")	
Time	Position	Applicant's Actions or Behavior	
Reg VIV	be cause the sale cause the sale cause the mill manual will be not so to sale the sale cause the	EVALUATOR NOTES: Se inserted when power has been reduced to noticed until a power reduction of performed for the next malfunction for 11 Main Feeling - The following annunciator will alarm when a high level deviation of 5% occurs in 12 SG during the turbine load decrease performed for the next malfunction: the melforation aformed for the next malfunction: the melforation of 5% occurs in 12 SG during the turbine load decrease performed for the next malfunction: the melforation aformed for the next malfunction: the melforation of 5% occurs of the next malfunction: the melforation of 5% occurs of the next malfunction. The melforation of 5% occurs of the next malfunction is inverted: The following annunciator will alarm when a high level deviation of 5% occurs of 5	vera Per
		Concur. Changes incorporated. incorporated. Muller	

Op-Tes	t No.: S	cenario No.: 3 Event No.: 4 Page 5 of					
Event D	Event Description: High stator temperature on 11 Main Feedwater Pump (requires turbine load decrease to 330 MWe, since will need to shutdown pump). 11 Main Feedwater Pump trip during load reduction (will need to rapidly reduce turbine load).						
Time	Position	Applicant's Actions or Behavior					
		EVALUATOR NOTE: The following annunciator will alarm when the malfunction is inserted: 47010-0401,"11 FEEDWATER PUMP MOTOR STATOR HI TEMP"					
	SRO	DIRECT or maintain overview of actions for high stator temperature alarm per ARP 47010-0401, "11 FEEDWATER PUMP MOTOR STATOR HI TEMP"					
		PERFORM actions for high stator temperature alarm per ARP 47010-0401, "11 FEEDWATER PUMP MOTOR STATOR HI TEMP": - VERIFY stator temperature high by observing the redundant stator temperatures - DIRECT local operator to verify motor coolers in operation AND that cool air is being directed on the motor: (Panel 130 located near the 11Main FWP) - 11 FW Pump 11A Cooling Fans - Panel 130, Circuit 1 - 11 FW Pump 11B Cooling Fans - Panel 130, Circuit 2					
-	EXALUATOR	CUES: The local operator reports that; The motor coolers are not working and the pump is starting to get hot. It must be something internal to make the so					
		IF crew is hesitant to start reducing power right away, THEN increase stator temperature on ERCS (computer) by 20°C AND insert the following annunciator alarm: -47010-0101, "11 FEEDWATER PUMP OVERLOAD"					
		(to 140°C)					
		Concur. Charges incorporated Conhumenter. N Value					

Op-Tes	t No.: S	cenario No.: 3 Event No.: 4	Page <u>6</u> of		
Event Description: High stator temperature on 11 Main Feedwater Pump (requires turbine load decrease to 330 MWe, since will need to pump). 11 Main Feedwater Pump trip during load reduction (will need to rapidly reduce turbine load).					
Time	Position	Applicant's Actions or Behav	rior		
	SRO	In preparation for stopping the 11 Main FWP, DIRECT power decrease to a turbine load of 3 1C1.4 AOP1, "Rapid Load Reduction - Unit 1"	30 MWe per		
	RO	BORATE the RCS as necessary to maintain of the insertion limit and to control delta I within li - PLACE the Makeup Mode Selector Switch to SET YIC-110, "Boric Acid Integrator" to the SET HC-110, "Boric Acid Flow Controller" at the flow desired (IF desired, THEN PLACE "MANUAL" and adjust output for the desired. - Momentarily PLACE the Boric Acid Makeup	mits: o "BORATE" quantity desired tuto setpoint dial to HC-110 to d flow)		
	ВОР	REDUCE turbine load in Automatic <u>OR</u> Manual - Automatic: • SELECT the desired load rate on the Turbin • SET the desired turbine load on the "SETTI Turbine EHC Panel using the reference contour • DEPRESS the turbine control "GO" pushbut - Manual: • DEPRESS the turbine control "TURBINE Mushbutton until the is reached.	I: ne EHC panel ER" display on the trol pushbuttons tton ANUAL" pushbutton		

Op-Te:	st No.: S	Scenario No.: 3 Event No.: 4 Page 7 of	
Event I	(re pui 11	gh stator temperature on 11 Main Feedwater Pump equires turbine load decrease to 330 MWe, since will need to shutdown mp). Main Feedwater Pump trip during load reduction ill need to rapidly reduce turbine load).	
Time	Position	Applicant's Actions or Behavior	
		EVALUATOR NOTE: The 11 Main Fe ducker Pump trip will be the following annunciator will alarm when the 11 Main Feedwater Pump Trip malfunction is inserted: - 47010-0101, "11 FEEDWATER PUMP LOCKED OUT"	inserted ing the down.
	SRO	DIRECT actions to reduce turbine load to less than 330 MWe per ARP 47010-0101, "11 FEEDWATER PUMP LOCKED OUT" and 1C1.4, "Rapid Power Reduction - Unit 1"	
	ВОР	REDUCE turbine load in Automatic <u>OR</u> Manual to less than 330 MWe: - Automatic: - SELECT the desired load rate on the Turbine EHC panel - SET the desired turbine load on the "SETTER" display on the Turbine EHC Panel using the reference control pushbuttons - DEPRESS the turbine control "GO" pushbutton - Manual: - DEPRESS the turbine control "TURBINE MANUAL" pushbutton - DEPRESS the "CV ▼ " pushbutton until the desired turbine load is reached	
	ВОР	CONTROL 12 SG level with its FW Reg Valve controller in "MANUAL"	
	RO	BORATE the RCS as necessary to maintain control rods above the insertion limit and control delta I within limits: - PLACE the Makeup Mode Selector Switch to "BORATE" - SET YIC-110, "Boric Acid Integrator" to the quantity desired - SET HC-110, "Boric Acid Flow Controller" auto setpoint dial to the flow desired (IF desired, THEN PLACE HC-110 to "MANUAL" and adjust output for the desired flow) - Momentarily PLACE the Boric Acid Makeup switch to "START"	
	SRO	<u>IF</u> the reactor trips, <u>THEN</u> go to 1E-0, "Reactor Trip or Safety Injection"	

(oncor. Charges incorporated (enhancements). NValue

Op-Test No.: Scenario No.: Event No.: <u>5.6</u> Page <u>8</u> of							
Event D	Event Description: (5) Feedwater line break on 11 SG inside containment. Requires entry into 1E-0 and then 1E-2. (6) Failure of turbine to AUTO trip on Reactor Trip (will require MANUAL turbine trip)						
Time	Position	Applicant's Actions or Behavior					
	SRO/BOP	DIAGNOSE the secondary line break: - Containment pressure increasing - Feedwater flow to 11 SG increasing (IF reactor is NOT already tripped)					
	SRO	DIRECT RO to manually trip the reactor (IF reactor is NOT already tripped)					
	RO	Manually TRIP the Reactor					
	SRO	TRANSITION to 1E-0, "Reactor Trip or Safety Injection"					
		1E-0, "Reactor Trip or Safety Injection"					
	SRO	DIRECT actions per 1E-0, "Reactor Trip or Safety Injection"					
	RO	VERIFY Reactor Trip or Manually Trip the Reactor: - Reactor trip and bypass breakers are open - Neutron flux is decreasing - Rod Position indicators are at ZERO - Rod Bottom lights are LIT					
	ВОР	VERIFY Turbine Trip (failure of turbine to AUTO trip) - VERIFY both turbine stop valves are closed CRITICAL TASK: Manually trip the turbine before a severe challenge (ORANGE path) develops to the INTEGRITY critical safety function status tree					
		VERIFY Both Safeguards Buses Energized					

Concur. Change jincorporand (enhancement).
Mulos

Op-Tes			
Event ((7)	Feedwater line break on 11 SG inside containment. Requires entry into 1E-0 and then 1E-2. Failure of SI to AUTO actuate (will require MANUAL actuation of SI) Failure of Containment Isolation to AUTO actuate on SI (will require MANUAL actuation of Containment Isolation)	
Time	Position	Applicant's Actions or Behavior	
	RO	1E-0. "Reactor Trip or Safety Injection" CHECK if SI is Actuated (failure of SI to AUTO actuate) CRITICAL TASK: Manually actuate Safety Injection	
	ВОР	VERIFY Safeguards Component Alignment : (failure of Containment Isolation to AUTO actuate on SI)	
\$ (0)		CRITICAL TASK: Manually actuate Containment Isolation CHECK IF WERIFY MSIVs are Closed (IX containment pressure is 17 paig) CHECK IF WERIFY Containment Instrument Air Valves are Closed (CV-31740 and CV-31741) (IX containment pressure is 17 paig)	to reflect conditions expected for this scenario
enhane	SRO	ANNOUNCE Reactor Trip and SI	
		NOTIFY Station Manager and Site Emergency Coordinator	
	ВОР	CLOSE CC Supply to SFP Cooling HXs (MV-32115)	!
	SRO	ENSURE communication with NRC is established within 1 hour	
	ВОР	OPEN Turbine HP Drains (CS-46392)	
		DIRECT Turbine Building Operator to stop the TB roof exhausters and isolate the MSRs per Attachment J	
		VERIFY SI Fow	
		VERIFY RHR Flow (here NO RHR flow due to high RCS pressure)	3-
		VERIFY > 200 gpm total AFW flow	Cohencement
		VERIFY > 900 psig on AFW Pumps Discharge	

Concur. Changer incorporated Walos

Op-Test No.: Scenario No.: _3 Event No.: _5 Page 10 o						
Event [Event Description: Feedwater line break on 11 SG inside containment. Requires entry into 1E-0 and then 1E-2.					
Time	Position	Applicant's Actions or Behavior				
	ВОР	1E-0, "Reactor Trip or Safety Injection" VERIFY Status of Equipment in Auto Action Guide (Table E0-1)				
		PLACE Steam Dump in "STEAM PRESSURE" Mode				
		EVALUATOR NOTE: RCS temperature will be < 547°F and decreasing in the next step				
	RO BOP	CHECK RCS temperature is stable at or trending to 547°F: - CONTROL AFW flow but NOT < 200 gpm until level restored in the 12 SG - VERIFY SG blowdown valves closed - IF cooldown continues and RCS temperature is < 535°F, THEN close MSIVs (if the MSIVs are NOT closed already)				
to reflect that BO Opents Expect thech	1. 1.5 1.6 1.6 1.6 1.6 1.6 1.6 1.6 1.6 1.6 1.6	CHECK RCP Cooling: - VERIFY CC flow to each RCP > 150 gpm - VERIFY thermal barrier outlet valves open (CV-31245 and CV-31246) - VERIFY seal injection flow to RCPs is normal				
Biren	RO	CHECK PRZR PORVs and Spray Valves: - VERIFY PRZR PORVs are closed - VERIFY PRZR Spray Valves are closed CHECK IF				
	SRO	TRANSITION to 1E-2, "Faulted Steam Generator Isolation"				
		Concur. Changes incorporated. MValor				

Op-Tes	t No.: S	cenario No.: <u>3</u> Event No.: <u>5</u> Page <u>11</u> of	
Event D		Feedwater line break on 11 SG inside containment. (Bequires entry into 1E-0 and then 1E-2) on Arthur of Safety II SGTR on 11 SG when SG is fully depressurized (350 gpm instantance) (Pequires entry into 1E-3 and then 1ECA-3.1)	hive SGTR
Time	Position	Applicant's Actions or Behavior	Come in earlier to
		1E-2, "Faulted Steam Generator Isolation"	allow Identifican
	SRO	DIRECT actions per 1E-2, "Faulted Steam Generator Isolation"	Via Rad Monitors.)
	BOP	VERIFY MSIVs and Bypass Valves are Closed HECK IF Either & Not Faulted: VERIFY 12 SG is NOT Faulted DENTIFY FAULT & C.	
- VERIF	RV, s closed	ISOLATE the Faulted 11 SG: - ISOLATE Main FW line - ISOLATE AFW flow - CLOSE steam supply valve from 11 SG to TD AFW Pump - VERIFY SG blowdown isolation valves are closed CRITICAL TASK: Isolate the 11 SG before transition out of 1E-2	
add to Substep E-2 pm	. \	CHECK CST Level > 10,000 gallons CHECK Secondary Radiation: - INITIATE periodic activity samples of both SGs - VERIFY secondary radiation is NOT normal - TRANSITION to 1E-3, "Steam Generator Tube Rupture"	
		Concur. Changes incorporated. Mulos	

	Op-Test No.: Scenario No.: _3 Event No.: _9 Page _12 of Event Description: SGTR on 11 SG when SG is fully depressurized. Requires entry into 1E-3 and then 1ECA-3.1)					
Time	Position	Applicant's Actions or Behavior				
		1E-3, "Steam Generator Tube Rupture"				
	SRO	DIRECT actions per 1E-3, "Steam Generator Tube Rupture"				
	RO	CHECK if Should VERIFY RCPs are NOT Required to Be Stopped (enhanced to Be Stopped)				
	SRO	IDENTIFY that 11 SG is Ruptured				
	ВОР	ISOLATE Flow from Ruptured 11 SG: - VERIFY 11 SG PORV controller set in Auto at 1050 psig - CHECK 11 SG PORV closed - CLOSE steam supply valve from 11 SG to TD AFW Pump (already closed in E-2) - VERIFY 11 SG blowdown valves closed (already closed in E-2) - CLOSE 11 SG MSIV and bypass valve				
	SRO	VERIFY AFW flow to 11 SG Should Remain Isolated (since 11 SG is also faulted)				
	RO	CHECK PRZR PORVs and Block Valves: - VERIFY PRZR PORVs are closed - VERIFY at least one PRZR PORV block valve is open				
	BOP	VERIFY 11 SG is Faulted and Isolated				
		CONTROL AFW flow to maintain 12 SG Narrow Range Level between 5% and 50% (Wide Range Level between 50% and 59% for Adverse Containment)				
		RESET SI				
		RESET Containment Isolation				
		ESTABLISH Instrument Air to the Containment				

Concur. Changes incorporated, Millon

Op-Test No.: ____ Scenario No.: __3 Event No.: 9 Page _13 of _ Event Description: SGTR on 11 SG when SG is fully depressurized. Requires entry into 1E-3 and then 1ECA-3.1. Time **Position** Applicant's Actions or Behavior 1E-3, "Steam Generator Tube Rupture" VERIFY Safeguards Buses are Energized by Offsite Power BOP CHECK IF

VERIFY RHR Pumps are Required to be Left Running

STOP RHR Running VERIFY 11 SG Pressure is < 210 psig SRO TRANSITION to 1ECA-3.1, "SGTR with Loss of Reactor Coolant: Subcooled Recovery* LECA-3.1, " SETR with Lass of Reactor Codent : Subcoded DIRECT actions per 1ECA-3.1, "SGTR with Loss of Reactor Recovery SRO Coolant: Subcooled Recovery" TERMINATE SCENARIO when transition to IECA-3, 1 is made RESET SI (was already reset in 1E-3) BOP RESET Containment Isolation (was already reset in 1E-3) Terminate Scenatio ESTABLISH Instrument Air to Containment Courtier since : (was already established in 1 E-3) D Reincider of VERIPY all AC Buses Foorgized by Offsite Power steps are mastly venflections CHECK if Containment Spray Pumps Should be Stopped: IF CS Pumps are running AND containment pressure is 3) No dribigal < 20 psig, <u>THEN</u>: stord left. RESET/containment spray signal 3) Scenaro time STOP CS Pumps length is already VERIEX AFW flow to 11 SG Should Remain Isolated adequate. (since 11 SG is also faulted) VERIFY RHR Pumps are Required to he Left Running

Concur. Charges in corporated.
Molalos

Op-Test No.: _____ Scenario No.: _3_ Event No.: _9_ Page <u>14</u> of _ Event Description: SGTR on 11 SG when SG is fully depressurized. Requires entry into 1E-3 and then 1ECA-3.1. Time **Position** Applicant's Actions or Behavior 1E-3, "Steam Generator Tube Rupture" ESTABLISH Charging Flow: RO - ALIGN charging pump suction to the RWST (OPEN MV-32060) ESTABLISH maximum charging flow VERIFY 11 SG is Faulted and Isolated **BOP** CONTROL AFW flow to maintain 12 SG Narrow Range Level between 5% and 50% (Wide Range Level between 50% and 59% for Adverse Containment) INITIATE RES Cooldown to Cold Shutdown: MAINTAIN cooldown rate in RCS cold legs < 100°F/HR DUMP steam to condenser from the 12 SG **TERMINATE SCENARIO** when RCS cooldown is established Delete page.
Terminate proposition to made.

after transition made. Concer. Charge incorporated.

SCENARIO #3

Initial Conditions:

Unit 1:

- add to reflect
 add to reflect
 scenariondition 100% Power, End of Cycle, Equilibrium Xenon, RS born = 157 ppm
- Breaker 16-10 (Bus 16/Bus 26 Bustie) is OOS
- Steam Generator tube leakage of 4 GPD in 11 SG

Unit 2:

100% power steady state operation

Charge red.

Turnover:

- The 11 and 13 Heater Drain Pumps are presently running
- The 13 HD Pump was just started and the 12 HD Pump was shutdown so that preventive maintenance can be performed on the 12 HD Pump

Add another page for NOTES for simultar operator for initial sety for this scenario.

Appendix D

Scenario Outline

Form ES-D-1 (R8, S1)

Facility	/: <u>Prairie</u>	Island	Scenario No.: _4 Op-Test No.:	7			
Exami	ners:		Operators:				
J							
Initial Candidan III II							
Illitial Conditions: Unit 1: 50% power Middle of Cyclo Equilibrium V							
<u> </u>		JS LUM MAIN	15 Of 2 /2 hour clock assessed to the contract of the contract	to Bol			
				المرامة المرامة			
		TABA IONING		/affect			
9,,,, 2,	100 /8 DOW	rer steady s	tate operation	1/3000			
Turnov	er: Perfor	m nower inc	Propos on I laik 4 A. Access				
1C1.4.	"Unit 1 Pow	er Operatio	crease on Unit 1 to 100%. Are presently at Step 5.21.E of				
"Unit 1	Feedwater	Svstem" S	on" at the step to start the second feedwater pump per 1C28.2. Steps 5.5.1 through 5.5.8 of Section 5.5 of 1C28.2 have been				
comple	ted in prepa	ration for s	tarting the 12 FW Pump. A local operator is available by the				
<u>12 FW</u>							
	FA	dd Makine	as Numbers based on licenses input)				
Event		1	on themse input i				
No.	Malf.	Event	Event				
110.	1 100.	Type*	Description				
1	 	N(BOP)	Start 12 Main Feedwater Pump				
2	0.40.2	R(RO)	Reactor power increase				
3	8X213	I(BOP)	11 SG pressure channel 4DT 400 6 11	مار			
	(TR6 3)	\	11 SG pressure channel 1PT-468 failure high (11 SG PORV opens, must manually close PORV)	Allow.			
4	RX 206	1/00)		A Cho wil			
4	1 '	I(RO)	Pressurizer level channel 1L-428 failure low	A leg of po			
	(TRG 4)		(letdown isolates, PRZR heaters deposition and Oct	L'en Ster			
//	RC14 (2 seeps)			\sim			
5	RC14	C(RO)	RCS leak (30 gpm). Requires entry into 164 AOD1 30-150	Jec.			
76/	(100%)	M(ALL)	RCS leak (30 gpm). Requires entry into 164 AOP1. 30-150. Small break LOCA. (Requires use of E-0, E-1, and ES-1.1)	7150 54			
~			Small break LOCA. [Medulines use of E-0, E-1, and ES-1.1]	700317			
7 8	0146924	C(BOP)	Bus 16 deenergizes due to breaker failure from OT 44				
	(TRG7)		udisionilei, with a concurrent sequencer failure Discol				
	D GOZB		The state of the s				
ĺ	(Time O)		Dus to from that transformer her 1020 5 ACDS L L	10			
j	(me of		TO THE THE PARTY OF THE PARTY O				
			degraded core cooling due to no high head SI flow, since have no SI Pumps or PD Charging Pumps).				
æ		O/DOS:					
	+	C(BOP)	11 RHR pump does not AUTO start on St delete event.				
			(Will require manual start of pump)				
(N)orma	l, (R)eacti	vitv. (I)net	trument, (C)omponent. (M)ajor				
· · · · · ·			trument, (C)omponent, (M)ajor				
6	RP07	C(RO)	ATW 5 Creactor tripo will work from AMSA C/DSS sun	$\overline{}$			
•		- (no.)	LITTO A CHECKEN SAILS MILL MAK LIGHT LAND SM	te h			
	(Time 0)			j			
_ ^11.	1	Add hu	al Critical Track for scenerio.				
-/-	this arene	- 1 60m / / / /	incorporated. (oncur. (ornine jucorporated. Mila	nts			
			incorporated.	1.			
			' Ala	l Or			

0-6% (1845) 6-30%

Op-Test No.: ____ Scenario No.: __4 Event No.: __1 Page _1_ of __ Event Description: Start 12 Main Feedwater Pump Time **Position** Applicant's Actions or Behavior DIRECT BOP to start the 12 Main Feedwater Pump and maintain **SRO** overview of plant operations **BOP** Start the 12 FWP per 1C28.2, Section 5.5, "Starting a Second Feedwater Pump" starting at step 5.5.9: - PLACE control switch CS-46419 to the "START" position AND HOLD until CV-31875, "12 FWP RECIRC VLV" is FULL OPEN DISTCT loul CLOSE the second FWP warm-up valve F-22-4, "12 FWP PMP WARMUP LINE" DIRECT local operator to check the following indications for the 12 FWP: VERIFY seal water temperature is increasing to or being CUE: The local operator repo maintained at ≈ 150°F OBSERVE no evidence of steaming or external leakage AND that warmy Valve F-22-4 OBSERVE seal water leakage is on automatic control (no is closed bypass flow) VERIFY lube oil pressure > 15 psig VERIFY the auxiliary lube oil pump stops • THROTTLE the lube oil cooler cooling water outlet valve or Value # 22-4 13 outlet bypass valve to control lube oil outlet temperature at 100-125°F a local valve • VERIFY 12 FWP discharge pressure is ≈ 1200 psig · CHECK vibration on the local Reliance vibration panel for the 12 FWP, step-up gear, and motor (Vibrations should feel steady to the fingertips) CUE: The local operator reports that all indications are normal for the 12 FWP Concur. Comment incorporated. I Valor

Op-Test No.:	Scenario No.:	4	Event No.: 2	_	Page	_2_ of

Event Description: Reactor power increase

Time	Position	Applicant's Actions or Behavior				
	SRO	DIRECT actions per 1C1.4, "Unit 1 Power Operation" and maintain overview of plant operations				
	ВОР	INCREASE turbine load: - SELECT the desired load rate on the Turbine EHC panel - SET the desired turbine load on the "SETTER" display on the Turbine EHC Panel using the reference control pushbuttons				
	RO	 INITIATE an alternate dilution of the RCS per C12.5 as necessary: PLACE the Makeup Mode Selector Switch to "ALTERNATE DILUTE" SET YIC-111, "Reactor Makeup Water Batch Integrator" to the quantity desired IF desired,				
	ВОР	WHEN Tavg shows an increase , <u>THEN</u> DEPRESS the turbine control "GO" pushbutton				
	RO	MAINTAIN Tavg within the desired ± 1.5°F band				
	ВОР	As power is increased, ADJUST the following as necessary: - HD Pump speed - SG blowdown				

Op-Test No.:	Scenario No.: _	4	Event No.: 3	Page <u>3</u> of
	· · · · · · · · · · · · · · · · · · ·			· ~3~ <u>~~</u> · · <u>~</u>

Event Description: 11 SG pressure channel 1PT-468 failure high (11 SG PORV opens, must manually close PORV)

Time	Position	Applicant's Actions or Behavior
	SRO/BOP	RECOGNIZE the failed transmitter by the following indications: - 11 SG pressure channel 1PT-468 failure high - Steam Flow indicator 1FI-464 failure high - 11 SG PORV opens
- - -		PLACE 11 SG PORV controller in "MANUAL" and CLOSE valve
	SRO	DIRECT actions per 1C51.1, "Instrument Failure Guide" for Turbine 1stage pressure channel 1PT-485 failure high
	BOP	PERFORM actions per 1C51.1, "Instrument Failure Guide" for
11	SG presived PT-	*Favg Loop 1B 1T-401 Channel Failure High: - VERIFY or place 11 SG PORV controller in "MANUAL" and CLOSE valve
		- VERIFY 11 SG level control operating properly in automatic
	SRO	REFER to the following Tech Spec requirements: - TS 3.5.B and Table 3.5-2B Functional Unit 1c
	BOP	EVALUATOR NOTE: The next step will probably NOT be performed due to 6) hours allowed before the bistables are required to be tripped. DIRECT trip of the following bistables: - 1PC-468-A, "LO/LO PRESS SI" - 1PC-468-B, "LO PRESS ALARM"
		CUE: IPC is available to trip the bistables from
		Consult.
		Charges incorporated. Charges incorporated.

eflect orrect moment failue rthis Event

Op-Test	t No.: Sc	cenario No.: 4 Event No.: 3 Page 4 of	_
Event D	Event Description: 11 SG pressure channel 1PT-468 failure high (11 SG PORV opens, must manually close PORV)		
Time	Position	Applicant's Actions or Behavior	_
Titing	SRO	IF the Thermal Power Monitor is selected to Calorimetric input, THEN perform the following: - CHECK TPM power unaffected by the steam pressure channel failure - IF affected, THEN CHANGE TPM constant K202 from "0" (Calorimetric input) to "1" (NIS input) per C41.4, "ERCS NSSS Applications Program" AND NOTIFY ERCS computer group INITIATE Work Order to repair instrument MAKE necessary log entries	

Emercinent

Op-Test No.:	Scenario No.: 4	Event No.:4_	Page _5_ of

Event Description: Pressurizer level channel 1L-428 failure low

(letdown isolates, PRZR heaters deenergize, and Charging Pump in

"AUTO" increases to maximum speed)

Time	Position	Applicant's Actions or Behavior
		EVALUATOR NOTE: The following annunciators will alarm when the malfunction is inserted: - 47012-0507, "PRZR LVL DEVIATION" - 47012-0607, "PRZR LO-LO LVL HEATERS OFF AND LETDOWN SECURED" - 47015-0203, "CHARGING PUMP IN AUTO HI/LO SPEED"
	SRO/RO	RECOGNIZE the failed transmitter by the following indications: - Pressurizer level channel 1L-428 failure low - Letdown isolation / PRZR heater cutoff - Charging Pump in "AUTO" increases to maximum speed
	SRO	DIRECT actions per 1C51.3, "Instrument Failure Guide" for Pressurizer level channel 1L-428 failure low
	RO	PERFORM actions per 1C51.3, "Instrument Failure Guide" for Pressurizer level channel 1L-428 failure low: - PLACE charging pump speed control in "MANUAL" AND ADJUST pressurizer level to setpoint - SELECT position "2-1" (WHITE-RED) on the PRZR Level Control Selector Switch - RESTORE pressurizer heaters (must be placed in OFF for about 10 seconds in order for breaker to be closed) - RESTORE letdown per C12.1, "CVCS Letdown, Charging and Seal Water Injection": - PLACE 1HC-130, "LTDN TEMP CONT" in "MANUAL" AND OPEN to 50% - PLACE 1HC-135A, "LTDN PRESS CONT" in "MANUAL" AND OPEN to 50% - ESTABLISH charging to Regen HX by Missive (ME-14-2 and the charging to Regen H
	V-31226 and	OPEN letdown orifice isolation valve while adjusting PCV OPEN letdown orifice isolation valve while adjusting PCV

RETURN pressure and temperature controllers to "AUTO"

opened Add more detail per staps in procedure C12, 1.

Charges incorporated. Charges incorporated.

Op-Tes	Op-Test No.: Scenario No.: 4 Event No.: 4 Page 6 of			
Event D	Event Description: Pressurizer level channel 1L-428 failure low (letdown isolates, PRZR heaters deenergize, and Charging Pump in "AUTO" increases to maximum speed)			
Time	Position	Applicant's Actions or Behavior	dithic	
	RO		51, S	
	SRO	REFER to the following Tech Spec requirements: - TS 3.5.B and Table 3.5-2A Functional Unit 11	ノ	
	RO	EVALUATOR NOTE: The next step will probably NOT be performed due to 6 hours allowed before the bistables are required to be tripped. DIRECT trip of bistable 1LC-428-A, "HI LEVEL TRIP"		
		INITIATE Work Order to repair instrument	hand	
		MAKE necessary log entries		
	CUE: I	(C will be there in one (1) how. The ICC Tech out in Training.		
		Comments incorporated. Comments Malor		

Op-Test	No.: Seescription: RC	Cenario No.: 4 Event No.: 5 Page 7 of (2 steps for RCS (eac) CS leak (30 gpm). Requires entry into 1C4 AOP1 20 sec.	
Time	Position	Applicant's Actions or Behavior	
	RO	DIAGNOSE the RCS leak: - Decreasing pressurizer level - Charging flow increase - Decreasing VCT level - VCT automatic makeup - Annunciator 47012-0507, "PRZR LVL DEVIATION" - Annunciator 47015-0203, "CHARGING PUMP IN AUTO HI/LO SPEED"	ADIATION
	SRO	DIRECT actions per 1C4 AOP1, "Reactor Coolant Leak" IF at any time RCS inventory can NOT be maintained by available charging flow, THEN DIRECT manual trip of the reactor AND go to 1E-0, "Reactor Trip or Safety Injection"	
	RO	START additional charging pumps as needed to control pressurizer level IF VCT level can NOT be maintained by the make-up system. THEN align charging pump suction to the RWST USE Control Board indications to determine approximate leak rate DETERMINE the location of the leak using Figure 1 EVALUATOR NOTE: The containment should be identified as the recation of the leak based on: Increasing radiation levels on 1R-11, 12, 2, or 7 Increasing containment temperature, pressure, humidity Sump A or C level alarms	k rete

Concur. Changes incorporated. MValor

H		cenario No.: 4 Event No.: 5 Page 8 of (2 Steps for RCS leak) S leak (30 gpm). Requires entry into 104 AOP1. D TO 30 Jen With Fame of 300 Jec.	
Time	Position	Applicant's Actions or Behavior	
into Red	SRO SRO Che Entry Chaid land Chaid lan		i de 200 Jec.
13 be	BOP	DIRECT actions to reduce turbine load per 1C1.4, "Rapid Power Reduction Junit 1." REDUCE turbine load in Automatic OR Manual: - Automatic: - IF desired, THEN place rod control in "MANUAL" - SELECT the desired load rate on the Turbine EHC panel - SET the desired turbine load on the "SETTER" display on the Turbine EHC Panel using the reference control pushbuttons - DEPRESS the turbine control "GO" pushbutton- - Manual:	
	RO	DEPRESS the "CV v" pushbutton until the desired turbine load is reached. INTIATE a negative reactivity addition. Using control rods above the insertion limit and control delta I within limits: PLACE the Makeup Mode Selector Switch to "BORATE" SET YIC-110, "Boric Acid Integrator" to the quantity desired SET HC-110, "Boric Acid Flow Controller" auto setpoint dial to the flow desired (IF desired, THEN PLACE HC-110 to "MANUAL" and adjust output for the desired flow) Momentarily PLACE the Boric Acid Makeup switch to "START" WIEN Tave shows a decrease, THEN deposit the turbine control.	the Wing :

Charges incorporated.
Charges incorporated.
Mules

li	Op-Test No.: Scenario No.:4_ Event No.:6,7 Page _9 of Event Description: (-Small break LOCA (Sequires use of E-0, E-1, and ES-1.1)		
Time	Position	Applicant's Actions or Behavior	
	RO	DIAGNOSE the small break LOCA: - Decreasing pressurizer level beyond the capability of available charging flow	
/	SRO	DIRECT RO to manually trip the reactor	
	RO	Manually TRIP the Reactor (failure of Reactor to trip from BOTH of the Reactor Top switches)	
	SRO	TRANSITION to 1E-0, "Reactor Trip or Safety Injection" — CRITICAL TAJK: Manually trip the reactor Wing the AMSAC DUS Control June	
	add Atu	Concur. Changes incorporated. Mular	

(500 gpm) on leaster Trip				
Byent D By Bus sequend Will nee	Op-Test No.: Scenario No.: Event No.: Page 10_ of Feent Description: (6) Small break LOCA (Requires use of E-0, E-1, and ES-1.1) Will need to reenergize Bus 16 from 1RY transformer per 1C20.5 AOP2, Since here NO			
(if do no	ot reenergize Bu	is 16, will need to go to FR-0.2 for degraded core cooling due to no		
HIGH-DE	ER Dump does	e have no SI Pumps or PD Charging Pumps).		
	li ii i painp aces	not AUTO start on SI (will require manual start of pump) of delete	1	
Time	Position	Applicant's Actions or Behavior	NOT	
			non	
	SRO	DIRECT actions per 1E-0, "Reactor Trip or Safety Injection"		
	RO	VERIFY Reactor Trip: - Reactor trip and bypass breakers are open - Neutron flux is decreasing - Rod Position indicators are at ZERO - Rod Bottom lights are LIT		
	ВОР	VERIFY Turbine Trip: - VERIFY both turbine stop valves are closed		
		EVALUATOR NOTE: Bus 16 is deenergized due to breaker failure from CT-11 transformer, with a concurrent sequencer failure. Diesel Generator D2 trips during start. VERIFY Both Safeguards Buses Energized: - INITITIATE action to restore Bus 16 (which is deenergized) per 1C20.5 AOP2, "Reenergizing 4.16 KV Bus 16" EVALUATOR NOTE: See Page 18 for actions to reenergize Bus 16 per 1C20.5 AOP2 CRITICAL TASK: Reenergize Bus 16 from 1RY transformer		
	RO	CHECK if SI is Actuated: - Manually ACTUATE Safety Injection (<u>IF</u> NOT already actuated)		
	ВОР	VERIFY Safeguards Component Alignment: - Manually START 11 RHR Pump CRITICAL TASK: Manually start 11 RHR Pump Senano.		
	add s cheeki	Materia for Safeguards Component Alignment Component Alignment Component Alignment		

Concur. Changes incorporated.

Nullar

Op-Test No.: ____ Scenario No.: __4 Event No.: ____ Pa

(500 gpm) on Realer Trip

Event Description: Small break LOCA (Requires use of E-0, E-1, and ES-1.1) Page _11 of _ Time **Position** Applicant's Actions or Behavior 1E-0, "Reactor Trip or Safety Injection" (MSIK should remain open, since HECK if WERIFY MSIVs are Closed (Micontainment pressure in 17 psig) BOP CHECK if VERIFY Containment Instrument Air Valves are Closed (CV-31740 and CV-31741) (valvershould remain open, since (Mccontainment pressure is 17 psig) SRO ANNOUNCE Reactor Trip and SI NOTIFY Station Manager and Site Emergency Coordinator **BOP** CLOSE CC Supply to SFP Cooling HXs (MV-32115) OPEN Turbine HP Drains (CS-46392) SRO DIRECT Turbine Building Operator to stop the TB roof exhausters and isolate the MSRs per Attachment J CUE: The TB roof exhausters are stopped and the MSRs are isolated per Attachment J VERIFY SI FOW (have NO SI flow due to NO SI programmy) **BOP** VERIFY RHR Flow Chave NO RHR flow due to high RCS pressure) VERIFY > 200 gpm total AFW flow VERIFY > 900 psig on AFW Pumps Discharge VERIFY Status of Equipment in Auto Action Guide (Table E0-1) PLACE Steam Dump in "STEAM PRESSURE" Mode

> Concur. Changes incorporated (enhancements). Nulla

Op-Test No.: ____ Scenario No.: __4 Event No.: ____ Pa

(570 pm) on Result Fig.

Event Description: Small break LOCA (Fequires use of E-0, E-1, and ES-1.1) Page <u>12</u> of _ Time **Position** Applicant's Actions or Behavior 1E-0, "Reactor Trip or Safety Injection" RO CHECK RCS temperature is stable at or trending to 547°F 806 **CHECK RCP Cooling:** - VERIFY CC flow to each RCP > 150 gpm - VERIFY thermal barrier outlet valves open (CV-31245 and CV-31246) - VERIFY seal injection flow to RCPs is normal RO CHECK PRZR PORVs and Spray Valves: VERIFY PRZR PORVs are closed VERIFY PRZR Spray Valves are closed 4 (enhancements CHECK if CHECK IF

VERIFY RCPs are NOT Required to Be Stopped (since have NO SI Pumps running) **BOP VERIFY SGs are NOT Faulted** VERIFY SG tubes are NOT Ruptured **SRO VERIFY RCS is NOT intact:** - TRANSITION to 1E-1, "Loss of Reactor or Secondary Coolant" Charges incorporated.
Charges incorporated.
Maloz.

		cenario No.:4_ Event No.:977 Page13 of	
Event D	Event Description: Small break LOCA. (Flequires use of E-0, E-1, and ES-1.1)		
Time	Position	Applicant's Actions or Behavior	
		EVALUATOR NOTES: The crew may enter 1FR-C.2, "Response to Degraded Core Cooling" depending on how long it takes to restore power to Bus 16 per 1C20,5 AOP2 See Page 20 for actions per 1FR-C.2	
	SRO	DIRECT actions per 1E-1, "Loss of Reactor or Secondary Coolant"	
	ВОР	VERIFY Steam Dump in "STEAM PRESSURE" Mode	
	RO	CHECK if RCPs are Required to be Stopped: - IF an SI Pump is running with flow indicated AND RCS pressure is < 1250 psig (1575 psig for Adverse Containment), THEN STOP both RCPs	
	ВОР	VERIFY SGs are NOT Faulted	
		CONTROL AFW flow to maintain SG Narrow Range Levels between 5% and 50% (Wide Range Level between 50% and 59% for Adverse Containment)	
	SRO	VERIFY Secondary Side Radiation is Normal	
	RO	CHECK PRZR PORVs and Block Valves: - VERIFY PRZR PORVs are closed - VERIFY at least one PRZR PORV block valve is open	
i		Charges incorporated. Charges incorporated. Malor	

,2 ikred this tenuri

Op-Test	Op-Test No.: Scenario No.: _4 Event No.: _5 Page _14 of		
Event D	Event Description: Small break LOCA (sequires use of E-0, E-1, and ES-1.1.)		
Time	Position	Applicant's Actions or Behavior	
		1E-1, "Loss of Reactor or Secondary Coolant"	
	BOP	RESET SI	
		RESET Containment Isolation	
	;	ESTABLISH Instrument Air to the Containment	
		EVALUATOR NOTE: IF Bus 16 power is NOT restored, THEN NO Charging Pump will have power. The crew should be attempting to restore offsite power to Bus 16 from 1RY transformer per 1C20.5 AOP2.	
	RO	CHECK power supply to Charging Pumps is energized by offsite power - ATTEMPT to restore offsite power to Charging Pumps - <u>WHEN</u> at least one charging pump is running, <u>THEN</u> ESTABLISH charging flow	
		VERIFY SI can NOT be Terminated at this time (since do NOT have RCS subcooling)	
	ВОР	VERIFY Containment Spray Pumps are Stopped	
		EVALUATOR NOTE: Will NOT be able to stop RHR Pumps in the next step until Bus 16 is restored and an SI Pump is running CHECK if RHR Pumps Should Be Stopped: - IF RCS pressure is > 250 psig (550 psig for Adverse Containment) AND RCS pressure is stable or increasing, THEN STOP both RHR pumps	
		Changes incorporated. Changes incorporated. Million	

Op-Test No.: ____ Scenario No.: ____ Event No.: _____ (500 mm) on Recursition Page _15 of _

Event Description:	Small break LOCA	Requires	use of É-0,	, E-1, and ES-1.1)	
--------------------	------------------	----------	-------------	--------------------	--

Time	Position Applicant's Actions or Behavior		
7111.0			
		1E-1, "Loss of Reactor or Secondary Coolant"	
	RO/BOP	CHECK RCS and SG Pressures	
	ВОР	CHECK if DGs Should Be Stopped	
		CHECK if Safeguards Cooling Water Pumps Should Be Stopped	
		CHECK if Outside Air Can Be Supplied to Control Room	
		VERIFY Containment Dome Recirculation Fans are Running	
	SRO	CHECK Auxiliary Building Radiation is Normal	
	SRO	DIRECT local operator to align Containment FCU Cooling Water Outlet Radiation Monitors R-16 and R-38: - DIRECT local operator to open valves RD-6 and 2RD-4-2 CUE: Valves RD-6 and 2RD-4-2 are open	
	ВОР	- VERIFY solenoid isolation valves SV-33384 and SV-33907 are open	
	ВОР	CHECK if Containment Hydrogen Recombiners Should Be Placed in Service	
	SRO	CHECK if RCS Cooldown and Depressurization is Required: - TRANSITION to 1ES-1.1, "Post LOCA Cooldown and Depressurization"	
		Concur. Changes incorporated.	

Op-Test No.: ____ Scenario No.: __4 Event No.: ____ (500 gpm) on Require Trip Page _16 of _ Event Description: Small break LOCA, (Fequires use of E-0, E-1, and ES-1.1) Time **Position** Applicant's Actions or Behavior 1ES-1.1, "Post LOCA Cooldown and Depressurization" **BOP** VERIFY all AC Buses Energized by Offsite Power **EVALUATOR NOTE:** Will NOT be able to stop RHR Pumps in the next step until Bus 16 is restored and an SI Pump is running CHECK if RHR Pumps Should Be Stopped: - IF RCS pressure is > 250 psig (550 psig for Adverse Containment) AND RCS pressure is stable or increasing, **THEN STOP both RHR pumps** RO **CHECK Charging Pump Status:** - ALIGN charging pump suction to RWST (OPEN MV-32060) - WHEN at least one charging pump is running, THEN ESTABLISH maximum charging flow **BOP CHECK Intact SG Levels:** - CONTROL AFW flow to maintain Narrow Range Level between 5% and 50% (Wide Range between 50% and 59% for Adverse Containment) INITIATE RCS Cooldown to Cold Shutdown: - MAINTAIN cooldown rate in RCS cold legs < 100°F/HR - DUMP steam to condenser **TERMINATE SCENARIO** when RCS cooldown is established (oncor. ircorporated. Malos

			จ
Op-Test No.: Scenario No.:4			
Event D	a qui titi ico	s 16 deenergizes due to breaker failure from CT-11 transformer, with oncurrent sequencer failure. Diesel Generator D2 trips during start. Il need to reenergize Bus 16 from 1RY transformer per 1C20.5 AOP2, do not reenergize Bus 10, will need to go to FR-C.2 for degraded re-cooling due to no high head SI flow, since have no SI Pumps or Charging Pumps).	FR-C, 2 would
Time	Position	Applicant's Actions or Behavior	for this
	BOP SRO	Reenergizing Bus 16 from 1RY Transformer EVALUATOR NOTE: The following annunciators will alarm when Bus 16 is lost and Diesel Generator D2 fails to start: - 47024-0204, "BUS 16 4.16 KV UNDERVOLTAGE" - 47024-0304, "BUS 16 4.16 KV DEGRADED VOLTAGE" - 47024-0504, "BUS 16 BKR 8 SOURCE FROM BUS CT 11 TRIPPED" - 47024-0806, "D2 EMERGENCY GENERATOR FAILURE TO START" RECOGNIZE the loss of bus 16, the failure of the Load Sequencer, and the trip of Diesel Generator D2 DIRECT actions to restore Bus 16 per the Alarm Response Procedures and 1C20.5 AOP2, "Reenergizing 4.16KV Bus 16"	Stenenic
		RECORD Control Room alarms associated with Bus 16 deenergization DIRECT local operator to determine bus protective relay targets and status of bus and breakers CUES: - Local operator reports: - There are NO relay flags present on Bus 16 (except for the UV relays in the sequencer cabinet) - There is NO apparent reason why the CT-11 breaker opened - IF Engineer contacted, THEN recommend reenergizing Bus 16 using 1RY transformer until the cause of the CT-11 breaker malfunction is determined EVALUATOR NOTE: IF the crew decides to try to energize Bus 16 from CT-11, THEN the CT-11 breaker will trip when trying to close in	

Changes incorporated.

Changes incorporated.

Milalox

Op-Test No.: ____ Scenario No.: __4 Event No.: __/8 Page _18 of _ Event Description: Bus 16 deenergizes due to breaker failure from CT-11 transformer, with a concurrent sequencer failure. Diesel Generator D2 trips during start. (Will need to reenergize Bus 16 from 1RY transformer per 1C20.5 AOP2. Inches No. fif do not reenergize Bus 16, will need to go to FR-C.2 for degraded start occling due to no high head SI flow, since have no SI Pumps or PD Charging Pumps). Time **Position** Applicant's Actions or Behavior Reenergizing Bus 16 from IRY Transformer por 1020.5 ACP 2 **SRO** DETERMINE that CT-11 feeder breaker to Bus 16 opened **BOP** PLACE Bus 16 Voltage Restoration Switch in "MANUAL" PLACE the three(3) Bus 16 feeder breaker closure selector switches in "MANUAL" PLACE Bus 16 loads in "PULLOUT" PLACE Bus 16 Synchroscope Selector Switch to "1RY" CLOSE Breaker 16-2 (Bus 16 Source from 1RY Transformer) to reenergize Bus 16 VERIFY Bus 16 between 4000-4400 volts PLACE Bus 16 Synchroscope Selector Switch to "OFF" RESTORE power to 480V Buses 121 and 122: - VERIFY Breakers 121A and 122A are open - VERIFY Breakers 121M and 122M are closed - CLOSE Breaker 16-4 (Bus 16 feed to 121M Transformer) to reenergize Bus 121 - CLOSE Breaker 16-11 (Bus 16 feed to 122M Transformer) to reenergize Bus 122 **RESTORE Bus 16 loads:** - START 12 SI Pump **CRITICAL TASK:** START 12 SI Pump Changer incorporated.

FR-C2

would NOT

be entered for this stenario.

Entrucement

Appendix D

Operator Actions

Operator Actions

Operator Actions

Operator Actions

Op-Tes	t Ne.: Sc	cenario No.: 4 Event No.: 7 Page 19 of			
Event D	Event Description: Bus 16 deenergizes due to breaker failure from CT-11 transformer, with a concurrent sequencer failure. Diesel Generator D2 trips during start. Will need to reenergize Bus 16 from 1RY transformer per 1C20.5 AOP2 (if do not reenergize Bus 16, will need to go to FR-C.2 for degraded core cooling due to no high head SI flow, since bave no SI Pumps or PD Charging Pumps).				
Time	Position	Applicant's Actions or Behavior			
		EVALUATOR NOTE: The crew may enter 1FR-C.2, "Response to Degraded Core Cooling" depending on how long it takes to restore power to Bus 16 per 1C20.5 AOP2.			
	1	1FR-C\2, "Response to Degraded Core Cooling"			
	SRO	DIRECT actions per 1FR-C.2, "Response to Degraded Core Cooling"			
	ВОР	VERIFY Proper SI Valve Emergency Alignment			
	RO	VERIFY SI Flow CHECK RCS Vent Paths: - VERIFY PRZR PORVs are closed - VERIFY at least one PRZR PORV Block Valve is open - VERIFY Reactor Head Vent Valves are closed CHECK RCP Status:			
	ВОР	- VERIFY at least one RCP is running CHECK RVLIS Dynamic Head Indication: - IF < 62% and decreasing (for 2 RCPs running), THEN REDUCE to one RCP running VERIFY SI Accumulator Isolation Valves are open			
		CHECK Intact SG Levels: - CONTROL AFW flow to maintain Narrow Range Level between 5% and 50% (Wide Range between 50% and 59% for Adverse Containment)			

Onerst Prye would Not be surano.

Appendix D

Operator Actions

Concer Comment Form ES-D-2 (R8,

Op-Test No.: Scenario No.: __4_ Event No.: _7_ Page _20 of Event Description: Bus 16 deenergizes due to breaker failure from CT-11 *fransformer, with a concurrent sequencer failure. Diesel Generator D2 trips during start. Will need to reenergize Bus 16 from 1RY transformer per 1C20.5 AOP2 (if do not reenergize Bus 16, will need to go to FR/C.2 for degraded core cooling due to no high head SI flow, since have no SI Pumps or PD Charging Pumps). Time **Position** Applicant's Actions of Behavior 1FR-C.2, "Response to Degraded Core Cooling" **BOP** DEPRESSURIZE SGs To 200 péig: - MAINTAIN cooldown rate in RCS cold legs < 100°F/HR DUMP steam using SG PØRVs CHECK RHR Pumps are Aunning <u>IF</u> either RCS hot leg temperature is < 390°F, <u>THEN</u> perform the following: **SRO** DIRECT local operator to unlock and energize the accumulator isolation valve breakers • RESET SI (was already reset in E-1) **BOP** CLOSE accumulator isolation valves (MV-32Ø71 and MV-320\(\chi2\) STOP/running RCP RO DEPRESSURIZE SGs To Atmospheric Pressure: **BOP** MAINTAIN cooldown rate in RCS cold legs < 100°F/HR DVMP steam using SG PORVs VERIFY SI Flow **SRO** WHEN SI flow is verified, THEN ISOLATE SI Accumulators: (IF NOT done in previous step) DIRECT local operator to unlock and energize the accumulator isolation valve breakers **BOP** RESET SI (was already reset in E-1) CLOSE accumulator isolation valves(MV-32071 and MV-32072) STOP running RCP

SCENARIO #4

Initial Conditions:

Unit 1:

المسيح على المسيح 50% power, Middle of Cycle, Equilibrium Xenon

Change to BOL, down't affect sceneurio

 11 SI Pump is OOS (on hour 16 of a 72 hour clock, expected back in 8 hours)

12 Charging Pump is OOS for overhaul

- Breaker 16-10 (Bus 16/Bus 26 Bustie) is OOS

Steam Generator tube leakage of 4 GPD in 11 SG

Unit 2:

100% power steady state operation

Turnover:

- Perform power increase on Unit 1 to 100%
- Are presently at Step 5.21.E of 1C1.4, "Unit 1 Power Operation" at the step to start the second feedwater pump per 1C28.2, "Unit 1 Feedwater System"
- Steps 5.5.1 through 5.5.8 of Section 5.5 of 1C28.2 have been completed in preparation for starting the 12 FW Pump
- A local operator is available by the 12 FW Pump to perform any required actions during the pump startup

Changes incorporated Malos

doesn't affect